	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	48	"material strength" near3 (detect$3 measur$3 evaluat$3)	USPAT	2002/09/30 09:56	
2	BRS	L2	30898	strength near3 (detect$3 measur$3 evaluat$3)	USPAT	2002/09/30 09:57	
3	BRS	L3	1979	2 and "peel strength"	USPAT	2002/09/30 09:57	
4	BRS	L4	0	3 and "fragility breaking"	USPAT	2002/09/30 09:58	
5	BRS	L5	0	2 and "fragility breaking"	USPAT	2002/09/30 09:58	
6	BRS	L6	877	2 and "breaking strength"	USPAT	2002/09/30 09:58	
7	BRS	L8	226	y and indenter	USPAT	2002/09/30 10:06	
8	BRS	L9	161	8 and test	USPAT	2002/09/30 09:59	
9	BRS	L13	0	(detect$3 measur$3 sens$3) near4 "charg$3 particles"	USPAT	2002/09/30 10:01	
10	BRS	L14	0	12 and (detect$3 measur$3 sens$3) near4 "charg$3 particles"	USPAT	2002/09/30 10:01	
11	BRS	L12	5	10 and 11	USPAT	2002/09/30 10:02	
12	BRS	L11	12	8 and "indentation depth"	USPAT	2002/09/30 10:04	
13	BRS	L10	15	8 and "indentation load"	USPAT	2002/09/30 10:05	
14	BRS	L15	3	7 and indenter	USPAT	2002/09/30 10:06	
15	BRS	L7	1979	2 and 3	USPAT	2002/09/30 10:09	
16	BRS	L16	0	"detectng charged particles"	USPAT	2002/09/30 10:19	
17	BRS	L17	8	"measuring charged particles"	USPAT	2002/09/30 10:18	
18	BRS	L19	0	18 and indenter	USPAT	2002/09/30 10:19	
19	BRS	L18	92	"detecting charged particles"	USPAT	2002/09/30 10:19	

	Error Definition	Errors
1		0
2		0
3		0
4		0
5		0
6		0
7		0
8		0
9		0
10		0
11		0
12		0
13		0
14		0
15		0
16		0
17		0
18		0
19		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	11108	Charg$ near3 (particle grain granuel particulate)	USPAT	2002/09/30 11:06	
2	BRS	L2	0	1 and 73/&7.ccls.	USPAT	2002/09/30 11:06	
3	BRS	L3	0	1 and 73/&7	USPAT	2002/09/30 11:06	
4	IS&R	L4	6070	(73/760-860).CCLS.	USPAT	2002/09/30 11:07	
5	BRS	L5	1	1 and 4	USPAT	2002/09/30 11:08	
6	BRS	L6	4	1 and "material testing"	USPAT	2002/09/30 11:09	

	Error Definition	Errors
1		0
2		0
3		0
4		0
5		0
6		0